

19 Agustus 2024

Nomor : 038/RSMU/PSP/SP/VIII/2024  
Lampiran : 1  
Perihal : Pengadaan Sapre part Shoe lift FUJITEC RS.Mata Undaan

Yth. **GM Umum & SDM Rumah Sakit Mata Undaan**  
Surabaya


Dengan hormat,

Menindaklanjuti hasil pemeriksaan teknisi FUJITEC pada pemeliharaan rutin tanggal 16 Juli 2024 dan merekomendasikan untuk penggantian spre part Safety Shoe lift pada surat penawaran No.MTQ167-24 SBY maka dengan ini kami Manager PSP mengajukan pengadaan part tersebut dengan rincian besaran biaya terlampir.

Pengajuan penggantian aki telah sesuai dengan usia pakai aki dan merupakan salah satu fitur keselamatan utama pada lift.

Demikian surat ini kami sampaikan, atas perhatian dan kerjasamanya diucapkan terima kasih.

Hormat kami,



Sudarto  
Manager PSP RS. Mata Undaan

Tulis



Kotak Masuk

471

### Penawaran Sparepart RS. Undaan No.MTQ167-24 SBY

Kotak Masuk x

Berbintang

Ditunda

Terkirim

Selengkapnya



**Surabaya Service** <service.sby@id.fujitec.com>

kepada saya, Sutiawan, Jolanda

Kepada Yth,  
RS Mata Undaan  
Jl. Undaan Kulon No. 17-19  
UP : Bapak Sudarto

Label

[Imap]/Drafts

[Imap]/Trash

Menindaklanjuti hasil callback yang telah dilakukan, terdapat rekomendasi penggantian sparepart. Maka dari itu kami kirimkan lam  
Demikian informasi yang bisa disampaikan, atas perhatian dan kerjasamanya dari Bapak kami mengucapkan terimakasih.

Salam hormat,

Agung Septa P.  
(0838-5452-9662)  
Service Sales

**FUJITEC**

**PT. Fujitec Indonesia (Lift & Escalator)**

Ruko Rich Palace Blok R No.23  
Jalan Mayjen Sungkono  
Surabaya



# FUJITEC

PT. FUJITEC INDONESIA  
WORK REPORT

TECHNICIAN: Yago Wijanarbo DATE: 16 Juli 2024  
 SITE NAME: RS Mata Undaan TIME: 14.00 TO 17.00  
 UNIT NO.: Pl. 1

WORKING DETAILS DESCRIPTION	Info Eng Mt Lubo setelah perpendatan Power dari PLN ke genset
ETC	70, 72, 78, 79
ACTION	- Cek Panel Kontrol - Cek CTL - Cek multibim - Cek GS - Cek Safety shoe
CAUSE	- Indikator Safety shoe kurang Presisi dan rubi ohm Jelek
SOLUTION	- Cleaning dan adjust Safety shoe
STATUS	. Lift job NORMAL  * Rekomendasi Perawatan switch safety shoe dan Kabel Safety shoe 7 m.

PAID   
 FREE   
 INCLUDE CONTRACT

CUSTOMER	ISSUER	CHECKER	APPROVER
			

Approve By Customer: .....  
 Date /Time: .....

FMT014A

# FUJITEC

## PT. FUJITEC INDONESIA

Perkantoran Grand Aries Niaga,  
Jl. Taman Aries Blok G1 No. 1A-1B  
Kembangan, Jakarta Barat 11620, Indonesia  
Telp. (021) 2931 9313/314/315 Fax. (021) 2931 9316  
Website : www.fujitec.com

## QUOTATION

To : **RS MATA UNDAAN**  
Jl. Undaan Kulon No. 17-19  
Surabaya  
Attn : Bapak Sudarto  
Site : **RS MATA UNDAAN**  
Email : [sudarto1785@gmail.com](mailto:sudarto1785@gmail.com)

Quotation No. : MTQ167-24 SBY  
Date : 05/05/2023  
Page : 1 of 1  
Validity : 30 days  
Supervisor : Alex Sutiawan

Tel :  
Fax :

Based on : Call Back  
Sales : Agung Sapta P

NO.	PART NAME	LIFT NO.	QTY	UNIT PRICE (IDR)	TOTAL PRICE (IDR)
A	<b>MATERIAL</b>				
	1 Switch Safety Shoe	BL1	2 Pcs	900.000	1.800.000
	2 Kabel Safety Shoe	BL1	7 M	150.000	1.050.000
<b>Sub Total</b>					<b>2.850.000</b>
<b>PPN 11%</b>					<b>313.500</b>
<b>Grand Total</b>					<b>3.163.500</b>

### Term & Conditions:

- Price above has not yet included Government VAT and following government provisions
- **Payment** : Full Payment (100%)
- **Delivery** : Max 3 months after received PO
- Order will be processed once PO is received, please send your PO via email to [service.sby@id.fujitec.com](mailto:service.sby@id.fujitec.com)
- This letter it's not a contract
- Price mentioned using the US Dollar currency which has been converted to IDR (Indonesian Ruplah) currency,
- Validity 30 days, Price stated may change without prior notice
- Based on Fujitec policy, the original spare part by Fujitec is our proprietary. After installed, old spare part will taken and destroyed by Fujitec.
- Converted price using : 1USD = IDR. 16.500, - and binds with tolerance of 3% (three per cent) change of prevailing exchange rate.
- Validity 30 days, Price stated may change without prior notice
- Based on Fujitec policy, the original spare part by Fujitec is our proprietary. After installed, old spare part will taken and destroyed by Fujitec.

**Best Regards,**



**Feby Jolanda**  
**Branch Manager**

- Surabaya Office : Ruko Rich Palace, Blok R No. 23. Jl. Mayjend Sungkono, Surabaya Telp: (031) 7390004
- Makassar : Jl. Monginsidi Baru Komplek Timurama Blok AB10 No.86 Kec.Rappocini, Kel. Balla Parang, Makassar Telp:0411-4098212