



Surabaya, 08 September 2021

Nomor : 028/RSMU/IPSRs/IX/2021
Lampiran : 2
Perihal : Pengadaan tombol Lift FUJITEC

Yth. **Direktur Rumah Sakit Mata Undaan**
Surabaya

Dengan hormat,

Berdasarkan laporan security pada tanggal 05 September 2021 dan rekomendasi hasil pengecekan oleh teknisi FUJITEC pada tanggal 06 September 2021 bahwa 3 pcs Hall Button dinyatakan rusak dan harus dilakukan penggantian.

Dengan ini kami Plt.Ka IPS RS Mata Undaan mengajukan Surat Pengajuan Pengadaan Tombol Lift FUJITEC.

Harga dan spesifikasi teknis terlampir berdasarkan pada penawaran yang di ajukan oleh pihak FUJITEC.
Demikian surat ini kami sampaikan, atas perhatian dan kerjasamanya diucapkan terima kasih.

Hormat kami,

Sudarto
Plt Ka IPSRS RS. Mata Undaan

QUOTATION

To : **RS MATA UNDAAN**
 Jl. Undaan Kulon No. 17-19
 Surabaya
 Attn : Bapak Sudarto
 Site : **RS MATA UNDAAN**

Quotation No. : MTQ019-21 SBY
 Date : 07/09/2021
 Page : 1 of 1
 Validity : 30 days
 Supervisor : Paryanto
URGENT

Email : sudarto1785@gmail.com
 Tel :
 Fax :

Based on : Call Back
 Sales : Brian

NO.	PART NAME	LIFT NO.	QTY	UNIT PRICE (IDR)	TOTAL PRICE (IDR)
I	MATERIAL				
1	Hall Button tipe HAS 12000A	P2	3 Pcs	995,000.00	2,985,000.00
Subtotal					2,985,000.00
Disc 5%					149,250.00
Total					2,835,750.00
PPN 10%					283,575.00
GRAND TOTAL					3,119,325.00

Term & Conditions:


- Price above is include Government VAT 10%
- **Payment** 30 days after delivery
- **Delivery** : Max. 4 months after received PO
- Order will be processed once PO is received, please send your PO via email to maintenance@fujitec.co.id
- This letter it's not a contract
- Price mentioned using the US Dollar currency which has been converted to IDR (Indonesian Rupiah) currency,
- Converted price using : 1USD = IDR. 14.500.00, - and binds with tolerance of 5% (five per cent) change of prevailing exchange rate.
- Validity 30 days, Price stated may change without prior notice

Best Regards,

Feby Jolanda
 Branch Manager



RSMATA
UNDAAN



Undaan Kulon 19
Surabaya 60274, Indonesia

T +6231 5343 806, 5319 619
F +6231 531 7503
E info@rsmataundaan.co.id

f Rumah Sakit Mata
Undaan Surabaya

@ [rs.mataundaan](https://www.instagram.com/rs.mataundaan)

rsmataundaan.co.id

DATE: 6 - Sept - 2021



TECHNICIAN: Yoggy

TIME: 11:00 TO 12:00

SITE NAME: PS Mata Undaan

UNIT NO.: 2

WORKING DETAILS / DESCRIPTION	Tombol turun Lantai 2 tidak berfungsi
E/C	-
ACTION	Cek hall button Lantai 2. Cek hall button All floor
CAUSE	Hall button Lantai 2 rusak.
SOLUTION	Perlu penggantian hall button type HSA12000.
STATUS	Open. Sementara hall button Lantai 2 arah turun ditukar hall button Lantai 6. * Total hall button yang rusak di Lift no2 <u>5 per</u>

CUSTOMER	ISSUER	CHECKER	APPROVER
 Sudarto	 Yoggy		